SERVICE DEPARTMENT BULLETIN

BULLETIN #97252

GENERAL CLASSIFICATION: Game Boy pocket AC adapter (P/N 35540)
SPECIFIC SUBJECT: Problem with contact in power jack

All Game Boy pocket AC adapters subject to this notice will cause the Game Boy pocket to work intermittently. The defective AC adapter can be identified by four small indentations in the side of the connector that plugs in to the Game Boy pocket.

The improved version will have five indentations instead of four (as illustrated below).

Repair Action

In warranty/Out of warranty - Exchange the AC adapter (P/N 35540) and submit warranty claim form to Nintendo. No proof of purchase required. Mark the claim form "Special Warranty" Service Bulletin #97252.



Bad



Good